

## Lake & Wetland Assessment Report

December 12<sup>th</sup>, 2023

Weather conditions: Sunny 58°F

Tesoro West

Water body	Condition	Mitigation measures
Lake 2a	Ok	N/A
Lake 2	Ok	N/A
Lake 3	Ok	N/A
Lake 4	Ok	N/A
Lake 6	Ok	N/A
Lake 7A	Ok	N/A
Lake 7	Ok	N/A
Lake 8	Ok	N/A
Lake 9	Ok	N/A
Lake 10	Ok	N/A
Lake 11A	Ok	N/A
Lake 11	Ok	N/A
Lake 12	Ok	N/A
Lake 13	Ok	N/A
Lake 14	Ok	N/A
Lake 15	Ok	N/A
Lake 15A	Ok	N/A
Lake 16	Ok	N/A
Mitigation Cell	Ok	N/A
Water Feature	Algae	Algae needs to be sprayed

- **Satisfactory Condition:** All lakes and the mitigation cell are in good condition with no significant issues reported.
- **Vegetation Concerns:** The water feature requires immediate attention due to the presence of algae, respectively.

Tesoro East

**Lakes:**

Location	Condition	Mitigation Measures
Clubhouse Lake	Ok	N/A
Lake 1	Ok	N/A
Lake 2	Ok	N/A
Lake 3	Ok	N/A
Lake 4	Ok	N/A
Lake 5	Ok	N/A
Lake 6	Ok	N/A
Lake 7	Ok	N/A
Lake 8	Ok	N/A
Lake 9	weeds	Weeds need to be sprayed
Lake 10	Ok	N/A
Lake 11	Ok	N/A
Lake 12	Ok	N/A
Lake 13	Ok	N/A
Lake 14	Ok	N/A

**Wetlands:**

Location	Condition	Mitigation measures
Wetland 1	Cattails	Cattails need to be sprayed
Wetland 2	Ok	N/A
Wetland 3	Ok	N/A
Wetland 4	Ok	N/A
Wetland 5	Ok	N/A
Wetland 6	Ok	N/A
Wetland 7	Ok	N/A
Wetland 8	Ok	N/A
Wetland 9	Cattails	Cattails need to be sprayed
Wetland 12	Ok	N/A
Wetland 13	Ok	N/A
Wetland 17	Ok	N/A
Wetland 18	Ok	N/A
Wetland 20	Cattails	Cattails need to be sprayed
Wetland 23	Ok	N/A
Wetland 24	Ok	N/A
Wetland 26	Ok	N/A
Wetland 42	Ok	N/A
Wetland 44	Ok	N/A
Mitigation cell	Cattails	N/A